



Affected products:

- **BeFREE 10 Touchcomputer Modules** (Ordering Codes BF10-xxx-xxx)
- BeFREE 20 Touchcomputer Modules (Ordering Codes BF20-xxx-xxx)
- **BeFREE 22 Touchcomputer Modules** (Ordering Codes BF22-xxx-xxx)

Due to Intel transitioning the C-0 stepping of the Intel Celeron J1900 processor to D-1 we would like to inform you that our BeFREE 10, BeFREE 20 and BeFREE 22 products will also be affected by this update.

In addition to the new processor stepping, BIOS will also be updated to the latest version but default settings will stay the same.

The change should be transparent to integrators and end-users. All operating system images should work without any change. There will be some driver installation activity in the background at first start, but no user intervention or internet connection is needed.

The existing functionality has been completely preserved. The phasing-in process is about to be started while the transition is expected to be completed within the next couple of months. It is going to be entirely seamless to the customers, both logistically (same ordering codes) and commercially (same prices).

In case of any related questions, please feel free to contact us at sales@tipro.si

Sincerely, Tipro Marketing & Sales